


# ENERGY STAR<sup>®</sup> Energy Performance Scorecard

**44.9**  
**kBtu per**  
**square foot\***

## Dover Highway Garage

For Year Ending	November 30, 2020
Property Address	136 East Duncan Hill Rd. Dover Plains, New York 12522
Primary Function	Transportation Terminal/ Station
Gross Floor Area (ft <sup>2</sup> )	7,000
Year built	1984
Energy Use per sq. ft.*	44.9 kBtu



### What is the ENERGY STAR Score?

The ENERGY STAR score rates commercial building's energy performance relative to similar buildings nationwide. Expressed as a number on a simple 1-100 scale, the score rates performance on a percentile basis: a building with a score of 50 performs better than 50% of its peers. Higher scores mean better energy efficiency, resulting in less energy use and fewer greenhouse gas emissions. If a 1-100 score for a specific building type has not been developed, Site Energy Use Intensity (EUI) will be displayed on this scorecard.

### Learn more at:

[energystar.gov/scorecard](https://energystar.gov/scorecard)

\*Site energy use