


ENERGY STAR[®] Energy Performance Scorecard

47.1
kBtu per
square foot*

Dover Highway Garage

For Year Ending	November 30, 2022
Property Address	136 East Duncan Hill Rd. Dover Plains, New York 12522
Primary Function	Transportation Terminal/ Station
Gross Floor Area (ft ²)	7,000
Year built	1984
Energy Use per sq. ft.*	47.1 kBtu



What is the ENERGY STAR Score?

The ENERGY STAR score rates commercial building's energy performance relative to similar buildings nationwide. Expressed as a number on a simple 1-100 scale, the score rates performance on a percentile basis: a building with a score of 50 performs better than 50% of its peers. Higher scores mean better energy efficiency, resulting in less energy use and fewer greenhouse gas emissions. If a 1-100 score for a specific building type has not been developed, Site Energy Use Intensity (EUI) will be displayed on this scorecard.

Learn more at:

energystar.gov/scorecard

*Site energy use